

# SERVICE BULLETIN



SERVICE DEPARTMENT, Technical Information on  Plymouth  Chrysler  Imperial

June 23, 1966


No. 66-86

This bulletin supplements information contained in Service Bulletin No. 66-75.

If it should become necessary to replace a power steering pressure hose on a 1962, 1963 or 1964 Chrysler equipped with air conditioning, replace with the new hose Part No. 2537811.

For replacement on a 1965 or 1966 Plymouth Fury equipped with air conditioning, use the new hose Part No. 2537613.

POLICY: INFORMATION ONLY

  
J. W. FARLEY  
Manager-Service  
CHRYSLER-PLYMOUTH DIVISION

## STEERING

NEW  
POWER  
STEERING  
PRESSURE  
HOSE

ALL  
1962  
THROUGH  
1964  
CHRYSLER  
MODELS  
AND  
1965-1966  
PLYMOUTH  
FURY  
MODELS  
EQUIPPED  
WITH  
AIR  
CONDITIONING  
P-2511-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	

THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS

CHRYSLER-PLYMOUTH DIVISION



**CHRYSLER**  
MOTORS CORPORATION