

SERVICE BULLETIN



SERVICE DEPARTMENT, Technical Information on Plymouth Chrysler Imperial

April 22, 1966

No. 66-74

AIR
CONDITIONING

New service compressor assemblies and compressor crankshaft packages have been released for factory air conditioning installations on 1965 Plymouth Valiant and Barracuda models equipped with a 273 cubic inch displacement engine and 1965 and 1966 Plymouth Fury models equipped with a 318 cubic inch displacement engine. The new compressors and crankshafts are especially designed for and should be used only on the indicated models. The part numbers are as follows:

<u>MODEL</u>	<u>ENGINE</u>	<u>COMPRESSOR</u>	<u>CRANKSHAFT PACKAGE</u>
1965 Valiant and Barracuda	273 C.I.D.	2815760	2815762
1965 and 1966 Fury	318 C.I.D.	2815761	2815755

NEW
COMPRESSOR
ASSEMBLIES
AND
CRANKSHAFT
PACKAGES

1965
PLYMOUTH
VALIANT
AND BARRACUDA
MODELS
AND 1965
AND 1966
PLYMOUTH
FURY
MODELS
EQUIPPED
WITH
FACTORY
INSTALLED
AIR
CONDITIONING

If it is necessary to replace a compressor assembly or crankshaft on one of these models, install the applicable part indicated on the chart.

POLICY: INFORMATION ONLY

J. W. Farley
J. W. FARLEY
Manager-Service
CHRYSLER-PLYMOUTH DIVISION

P-1785-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	

THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS

CHRYSLER-PLYMOUTH DIVISION



CHRYSLER
MOTORS CORPORATION